## JOB HAZARD CHECKLIST Prepared By: Hunter Thompson/Emily Norris Work Location: 600 Area, West of 200 West Project: Habitat Enclosure for Ground Squirrels This Job Hazard Checklist is issued as part of the SOW to communicate environmental, safety and health hazards, control measures, and requirements to prospective bidders. This checklist contains information obtained during preliminary planning for this project and does not address all hazards, control measure, and/or requirements. Additional information/details are provided to the subcontractor following contract award. This checklist is intended as a "safety starting point". **HAZARDS IDENTIFIED** ☐ Aerial Lifts Overhead Cranes in Area ☐ Asbestos Heavy Equipment Overhead Electrical Lines ☐ PCBs ☐ Biological/Sewage ☐ Hexavalent Chromium ☐ High Traffic Area ☐ Powder Activated Tools Beryllium ☐ Confined Space Entry Hoisting and Rigging □ Radiation Area ☐ Non Permit Confined Space ☐ Hot Work □ Respiratory ☐ Permit Confined Space □ Roof Access Required ☐ Hazards Associated with Identified **Underground Obstructions** □ Scaffolding Drowning Ladder Electrical ☐ Shoulder Work ☐ Lead ☐ Silica Mobile Equipment Falls ≥ 6 ft. Noise ☐ Fire Potential Stored Energy □ Forklifts Operating Rotating Equipment ∇ermin/Insects/Varmints Explosive Atmosphere ☐ Pressure ☐ Corrosives (specify the corrosive): Dust (specify what kind of dust): Other (specify): Ergonomic hazards from hand digging in soil. PERMITS/PLANS ANTICIPATED Check anticipated work permits/contractor submittals: ☐ Asbestos Work Permit ☐ Emergency Plan ☐ Beryllium Work Permit ☐ Energized Electrical Work Permit ☐ Hot Work Permit ☐ Confined Space Permit ☐ Fall Protection Work Plan □ Non-Emergency Hydrant Critical Lift Plan ☐ Fire Marshal Permits ☐ Tie-In Permit ☐ Silica Plan ☐ Electrical Installation Permit ☐ Electrical Utilities Disconnect Form A-6007-595. Hanford Site ☐ Test Plan(s) (specify what kind of Request Electrical Risk Assessment Test Plan) ☐ Flushing Plan ☐ Pressure Test Other (specify): Ecological permit, cultural permit **Facility Hazards:** ☐ Asbestos □ PCB ☐ Beryllium Lead ☐ WIDS ☐ Rodent Infestation Other (specify):

JOB HAZARD CHECKLIST (Continued)		
Prepared By: Hunter Thompson/Emily Norris	Work Location: 600 Area, West of 200 Wes	t
Project: Habitat Enclosure for Ground Squirrels		
Training:		
—	☐ Flagger Training omium ☐ Spotter Training ☐ EU LOTO ☐ Silica	Rigging
Competent Person/Qualified Person:  Fall Protection Excavation Confined Space Silica Asbestos Lead Scaffolding		
WALK-THROUGH ATTENDEES		
Hunter Thompson  Print First and Last Name	HUNTER THOMPSON (Affiliate) Pigitally signed by HUNTER Pate: 2021.11.17 17:00:18 -d  Signature Date	HOMPSON (Affiliate) >8'00'
Emily Norris	EMILY NORRIS (Affiliate) Digitally signed by EMILY Date: 2021.11.17 17:11:16	NORRIS (Affiliate) -08'00'
Print First and Last Name	Signature Date	
Print First and Last Name	Signature Date	
Print First and Last Name	Signature Date	
Print First and Last Name	Signature Date	
Print First and Last Name	Signature Date	
Till Tilst and Last Name	Signature	
Print First and Last Name	Signature Date	
Print First and Last Name	Signature Date	
Print First and Last Name	Signature Date	
Print First and Last Name	Signature Date	
Print First and Last Name	Signature Date	
Print First and Last Name	Signature Date	